ZyXEL

Driver/Utility Release Note

M-302

Driver version: 1.0.0.56/2.0.0

Date: APR. 06, 2006
Author:
Project Leader:

ZyXEL M-302 Standard Version release 2.0.0 Released Note

Date: APR. 06, 2006

Supported Platforms:

Windows 2000, Windows XP

Versions:

Driver Version : 1.0.0.56
Utility verison: 2.0.0

Known Issues:

1. To change transfer rate Non-administrator user have to un-plug and plug adapter.
2. TKIP encryption is able to connect to AES encryption AP; AES encryption is able to connect to TKIP AP.
3. In super G mode, Windows link speed show 108Mbps but utility Transmission Rate show 54Mbps.
4. Utilities that use Atheros solution can not exist in Windows at the same time.
5. Power saving function is not available
6. Does not support 802.11g in Ad-Hoc mode.
7. Site survey show WEP when AP is WPA2 only mode.
8. With some AP, site survey won't refresh SSID info of the AP you connected, even if you change SSID of AP. (Disable/Enable adapter can solve this problem.)

Features:

Modification in 2.0.0 | 04/06/2006
1. Driver Changed.
    1. First time released.

2. Utility Changed.
    1. Change version number from 2.0.0b3 to 2.0.0
    2. Change help file.