# Firmware Update For WJ.00.0F

Because of several new features are included into the new version and some memory allocation is changed. Before you update, please kindly check your current P2000W's firmware version. **If your P2000W's current firmware version is earlier than WJ000C**, please kindly follow the firmware update procedure in below. And this action will clear your current settings to factory default.

1. Access the web page and select the "Update S/W" page.
2. In the Update Firmware option, set **"Ignore S/W Identify Function"** to **Yes** and click the submit button.
3. In the Update System option click the Browse button [瀏覽...] to locate the new firmware file (**wj000f_img.ftp**). Click the Update button. Please note that the display of the Browse button depends on the language version of the Internet Explorer you are using.

ZyXEL P2000W VoIP Wi-Fi Phone

Update Firmware

TFTP IP Address	192.168.0.1
Ignore S/W Identify Function	○ No ● Yes

SUBMIT   CANCEL

Update System

Select File	C:\Documents and Settings\ray [瀏覽...] UPDATE

RESTART   Information Network OutBound Proxy SIP Proxy   SAVE

Phone Book Wireless DSP Setting TOS/DS System Update S/W

4. Once the update has been completed, the P2000W phone will automatically reboot.
5. **Reset P2000W to factory default:** Press the two buttons at the same time and power on the phone. The LCD screen will display "Load Default Factory".