by using this scan chain (setting watchpoints, breakpoints, registers, etc.).

Trace