

OpenCores

Contents

Contents	ii
Introduction.....	1
1.1 Framework.....	1
1.2 Simple GDB Session.....	1
Supported Features.....	2
2.1 hwatch Command.....	3
2.2 htrace Commands.....	4
2.2.1 htrace info.....	4
2.2.2 htrace trigger.....	4
2.2.3 htrace qualifier.....	4
2.2.4 htrace stop.....	5
2.2.5 htrace record.....	5
2.2.6 htrace clear records.....	6
2.2.7 htrace enable.....	6
2.2.8 htrace disable.....	6
2.2.9 htrace mode.....	6
2.2.10 htrace rewind.....	7
2.2.11 htrace print.....	7
2.3 Accessing spr Registers.....	7
2.3.1 info spr.....	7
2.3.2 spr.....	8
2.4 Extended Simulator Support.....	8
Protocols	9
2.1 JP1 Protocol.....	9
2.2 JP3 Protocol.....	10
Software Operation	11
4.1 Reset and Initialization of Remote Target.....	11
4.2 Communication with Target.....	12
4.3 Hardware Supported Breakpoints and Watchpoints	28
.....Ex Tj	26.426 0

2

Supported Features

This section covers debugging features supported by gdb, and describes special commands in detail. This section assumes C/C++ source language. Other language should use equivalent operators.

OR1k feature	Description	Command(s) in GDB	Comment
--------------	-------------	----------------------	---------

2.2 htrace2 Commands

of

TMS	Mode Select	1	Output	D2
TDI	Data Input	1	Output	D3
TDO	Data Output	1	Input	BUSY

2.2 JP3 Protocol

Unlike JP1, JP3 requires small amount of extra logic (e.g. PLD) on the board, but is six times faster.

OpenCores

GDB for OR1k

