

ZyXEL ZyAIR G-100 CD Version Release 1.2 Release Note

Date: August. 26, 2004

Supported Platforms:

Window98 SE, Window ME, Windows 2000 and Windows XP

Known issue:

1.Driver issue.

- 1.1 Odyssey SDK is left on the system after uninstallation. To remove Odyssey SDK, you need to go to control panel and manually select “uninstall” for this program.
- 1.2 Odyssey Client should not be installed on the same system that has Odyssey SDK. It will cause both program to stop functioning.

Features:

Modification in 1.0.0 | 05/10/2004

- 1. Formal Release-
 - 1.1 Support Wi-Fi WPA function
 - 1.2 Pass Microsoft WHQL